
Proper Drum & IBC Emptying

Do Not Remove Labels

Tight Heads


Raw Material



Pour out contents...Until drip dry...Replace all closures

Open Heads

Raw Material



Pour out contents...Until drip dry...Replace all lids & rings securely

IBCs must be "drip dry". No material should remain at the bottom or in the corners. Tip or tilt the IBC as necessary, using a block of wood under the side opposite of the valve. Thicker materials may require several hours draining, or draining overnight. Before returning, close valve, close fill cap, and do not remove labels.



Reusable Industrial Packaging Association (RIPA)

8401 Corporate Drive, Suite 450 Landover, MD, USA 20785

301-577-3786

www.reusablepackaging.org